

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E
T 28 N R 3 E

DESCRIPTION OF CORNER N 1/16 corner common to Sections 19 - 24

CORNER MONUMENT 1 3/4" pipe in block of concrete

DATE MONUMENT PLACED AND WITNESSED 6-3-70

WITNESSES TO CORNER..... 12" Tw. Poplar S 79 E 38.0'



10" Poplar N 66 W 11.2'

6" J. Pine S 60 E 79.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set midway and on line between 1/4 corner South and Section former North. Set to define state land boundary.

SURVEYOR'S SEAL

SIGNED *Rebecca J. Pettig* DATE 7-7-70
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68