

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 29 - 32

CORNER MONUMENT Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 6-3-70

WITNESSES TO CORNER.....



8" J. Pine S 50 E 14.8'

7" J. Pine S 23 W 15.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement between Section corners during a survey in this township. This position somewhat different than Schaaf location due to different section corners. Schaaf corner removed.

SURVEYOR'S SEAL

SIGNED Keith Ostling DATE 7-7-70
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68