STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

		OSCODA	COUNTY
	•	T <u>28 N</u>	R <u>2 E</u>
DESCRIPTION OF CORNER	W 1/16 corner common to	Sections 29 - 32	
CORNER MONUMENT	1" Pipe		
DATE MONUMENT PLACED AN	ID WITNESSED6-3-70		
	•••		
N	7" Oak	N 21 W	29.81
	8" J. Pine	S 36 W	11.4'
CIRCLE CORNER REGIST	AND ERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set midway and on line between 1/4 corner East and Section corner West.

SURVEYOR'S SEAL

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing