

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 1 E  
T 28 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 13-24-18-19

CORNER MONUMENT Set Dept. Mon.

DATE MONUMENT PLACED AND WITNESSED 6-15-70

WITNESSES TO CORNER..... 12" Tv R Pine N 64 W 90.0'



6" J. Pine N 40 E 56.5'

U.S. Army BM S 82 W 30.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this area. Found corner as established by Seeley in 1916 survey, in center of N-S road. Removed Schaaf pipe 5'+ Southwest, to avoid confusion. Other surveys based on Seeley location which is by far the oldest. Seeley NBT in place NE.

SURVEYOR'S SEAL

SIGNED

*Kenneth D. Ostling*  
REGISTERED LAND SURVEYOR 10068

DATE 7-17-70

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68