

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 18 - 19

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 6-15-70

WITNESSES TO CORNER.....



22" R. Pine Stp N 18 E 35.3'

12" Oak S 50 W 59.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored during a survey in this township. Found Seeley corner from 1916 survey, possibly set from U.S. evidence. Fence corner N-S-E. Schaaf pipe removed by others.

SURVEYOR'S SEAL

SIGNED *Llewellyn Pettibone* DATE 7-17-70
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68