

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY


T 28 N R 2 E

DESCRIPTION OF CORNER E 1/16 corner common to Sections 18-19

CORNER MONUMENT Set 1 1/2" x 18" pipe

DATE MONUMENT PLACED AND WITNESSED 6-15-70

WITNESSES TO CORNER.....



BT 6" Oak N 29 E 26.4'

BT 6" Oak N 83 E 37.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by standard survey procedure to mark state land boundary.

SURVEYOR'S SEAL

SIGNED *Kenneth D. Pettig* DATE 7-17-70  
REGISTERED LAND SURVEYOR

10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68