

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 9-10-15-16

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 6-30-70

WITNESSES TO CORNER.....



6" J. Pine S 20 E 45.1'

11" R. Pine S 60 W 103.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced cabin spike set by Caldwell as perpetuation of Seeley corner. Seeley claims to have had original witness in 1916 survey.

SURVEYOR'S SEAL

SIGNED

*Wm. H. DeWitt* DATE 7-17-70  
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68