## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

			OSCODA		COUNTY		
		1	28	N_	R.	2 1	<u>E</u>
DESCRIPTION OF CORNER _	1/4 corner on N. Boundary Se	<u>cti</u> or	1 4		<del></del>	<u> </u>	
CORNER MONUMENT	Set Department MOnument						
DATE MONUMENT PLACED AND	WITNESSED 6-30-70						
WITNESSES TO CORNER	•	·					
N							
<b>b</b>	6" Qak			s 76 W		18.	5'
<b> </b>	4" 0ak		1	N 32 E		8.:	<u>. '                                   </u>
	AND						
CIRCLE CORNER REGISTER	ED		<u> </u>				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Caldwell's Re-rod with Dept. Monument. Sk corner Section 33, T29NR2E is 34.9' West

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing