

✓

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER Sec. corner common to Sections 3-4 on N boundary of Twp.

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-16-70

WITNESSES TO CORNER.....



10" W. Oak S 13 W 23.2'

10" R. Oak S 40 E 19.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement survey of this township. Found old post bottom as established in a previous survey, possibly by Sealey or Smith. Posts were identified in 1935 Schaaf survey. Appear to have been accepted as proper location for corner.

Corner to Sec. 33-34, T29N-R2E is 9.2' East.

SURVEYOR'S SEAL

SIGNED *Timothy M. Wilting* DATE 12-16-70  
REGISTERED LAND SURVEYOR '10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68