

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER N 1/16 corner common to Sections 17 - 18

CORNER MONUMENT Set 1 3/4" pipe

DATE MONUMENT PLACED AND WITNESSED 12-15-70

WITNESSES TO CORNER.....



6" J. Pipe S 35 E 27.3'

5" J. Pipe S 12 W 20.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner was set by standard survey procedure during a retracement in this area.  
Set to mark state land boundary.**

SURVEYOR'S SEAL

SIGNED *Timothy H. Gething* DATE 12-22-70  
REGISTERED LAND SURVEYOR 18068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68