

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY  
T 28 N R 2 E

DESCRIPTION OF CORNER E 1/16 corner on N. Boundary Sec. 4, T28NR2E

CORNER MONUMENT 1 1/2" pipe in concrete block

DATE MONUMENT PLACED AND WITNESSED 12-15-70

WITNESSES TO CORNER..... 6" Oak S 72 E 13.2'



7" Oak S 6 W 27.6'

1-3/4" pipe West 12.85'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner was set by standard survey procedure to mark state land boundary.**

SURVEYOR'S SEAL

SIGNED *Penelope J. Williams* DATE 12-22-70  
REGISTERED LAND SURVEYOR 1968

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing