## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		OSCODA	COUNTY
		T	R 2 E
DESCRIPTION OF CORNER _	N 1/16 corner common	to Sections 8 6 9	
CORNER MONUMENT	Set 1-3/4" Pipe		
DATE MONUMENT PLACED AND	WITNESSED	12-18-70	
ITNESSES TO CORNER	•		
N N	8" J. Pine	N 63 E	48.01
	9" J. Pine	8 44 E	45,2'
	AND		
CIRCLE CORNER REGISTER	ED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by standard survey procedure to mark state land boundary.

SURVEYOR'S SEAL

SIGNED

(inly

2-27-70

DISTRIBUTION:

REGISTERED LAND SURVEYOR 1006

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing