


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER Section corner common to Sections 5 & 6
CORNER MONUMENT Set Department Monument
DATE MONUMENT PLACED AND WITNESSED 12-14-70
WITNESSES TO CORNER.....



8" J. Pine S 54 W 8.9'
7" Oak S 52 E 16.0'
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement survey of T28N-R2E. Found old wood post bottom at proper location from standard corner.

Corner to Sections 31-32, T29N-R2E is 23.1 East.

SURVEYOR'S SEAL

SIGNED *Kevin H. Helling* DATE 12-21-70
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68