

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 N.R. 2 E


Oscoda COUNTY

DESCRIPTION OF CORNER 1/4 corner on South Side Sec. 31

CORNER MONUMENT Set Cons. Dept. Mon.

DATE MONUMENT PLACED AND WITNESSED 8/27/68

WITNESSES TO CORNER.....



6" R. Pine N 41 E 122.7'

7" R. Pine S 46 E 96.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during survey of Section 31. Found 1½" pipe at corner as established in Schaaf survey of 1930s. Also conforms to previous surveys by County Surveyor, Seeley.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Belling* DATE 9/5/68
REGISTERED LAND SURVEYOR #10068