

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 28 N.R. 2 E  
T. 28 N.R. 1 E


Oscoda COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 31-36

CORNER MONUMENT Set Cons. Dept. Mon. below road

DATE MONUMENT PLACED AND WITNESSED 8/21/68

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

8" Tamarack N 54 W 40.7'

7" Cedar N 40 E 84.2'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during survey of Section 31. Found stake bottom below road surface, which checks old surveys by Schaaf and Seeley. Considered acceptable in this survey.

SURVEYOR'S SEAL

SIGNED

*Kenneth J. Wilby*  
REGISTERED LAND SURVEYOR #10068

DATE 9/5/68