

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 N.R. 2 E


Oscoda COUNTY

DESCRIPTION OF CORNER Sec. corner common to Sections 31-32 on S. boundary of Township

CORNER MONUMENT Set Cons. Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 8/21/68

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

6" J. Pine N 28 E 24.1'

5" R. Pine S 53 W 28.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during survey of Section 31. Found 1½" pipe at corner as established in 1934, Schaaf survey, which probably perpetuated a previous County Surveyor's survey. Best available evidence of proper location.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Gilling* DATE 9/5/68
REGISTERED LAND SURVEYOR #10068