

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 N.R. 2 E


OSCODA COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 33-34 on S. Boundary T28N-R2E

CORNER MONUMENT Set DNR Mon. below surface

DATE MONUMENT PLACED AND WITNESSED 5-13-69

WITNESSES TO CORNER.....



Old NBT 16" B. Oak N 25 W 13.7'

10" B. Oak N 86 E 71.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during retracement in this area. Found 1½" pipe with concrete at corner, as perpetuated by M. Schaaf from evidence by Seeley and Houghton. Probable restoration of U.S. corner.

SURVEYOR'S SEAL

SIGNED

Anneth D. Wilking
REGISTERED LAND SURVEYOR 10068

DATE

6/9/69