

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 N.R. 2 E


OSCODA COUNTY

DESCRIPTION OF CORNER 1/4 CORNER COMMON TO SECTIONS 21-22

CORNER MONUMENT SET. DEPT. MON., BELOW SURFACE

DATE MONUMENT PLACED AND WITNESSED 5-13-69

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

16" B. Oak N 45 E 74.1

12" B. Oak N 37 W 21.8

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set during a retracement in this township. Set corner by proportionate measurement between section corners. No evidence of a previous corner. Falls in center of N-S road.

SURVEYOR'S SEAL

SIGNED

Conrad A. Ostling
REGISTERED LAND SURVEYOR #10068

DATE

6-25-69