STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	OSCODA	COUNTY
	T <u>28</u>	R <u>2 E</u>
DESCRIPTION OF CORNER 1/4 CORNER COMMON TO SECTIONS	29-30	
CORNER MONUMENTSET_DEPT. MON.		
DATE MONUMENT PLACED AND WITNESSED <u>5-26-69</u>		
WITNESSES TO CORNER 5" R. Pine	S 50 E	59.5
7" Oak	N 83 W	22.1
6" R, Pine Stp.	N 65 E	26.1
AND 10" R. Pine Stp. CIRCLE CORNER REGISTERED	S 37 W	13.4

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during retracement in this township. Previously accepted by Seeley, Schaaf and Henning. One stump in place for possible U.S. witness.

SURVEYOR'S SEAL

SIGNED

hug DATE

6-25-69

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing