

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


OSCODA COUNTY
T 28 R 2 E

DESCRIPTION OF CORNER SEC. CORNER COMMON TO SECTIONS 20-21-28-29

CORNER MONUMENT SET DEPT. MON.

DATE MONUMENT PLACED AND WITNESSED 5-27-69

WITNESSES TO CORNER.....



7" R. Pine N 87 E 32.9

6" R. Pine N 09 E 53.1

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during survey in this area. Previously established by MarcMs Schaaf in 1930s. Schaaf record claims to have sites for U.S. witnesses. Seeley's corner disregarded at this location. Schaaf corner provides more equitable distribution of lands.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE 6-25-69
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68