

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD


OSCODA COUNTY  
T 28 R 2 E

DESCRIPTION OF CORNER SEC. CORNER COMMON TO SECTIONS 17-18-19-20

CORNER MONUMENT SET DEPT. MONUMENT

DATE MONUMENT PLACED AND WITNESSED 5-27-69

WITNESSES TO CORNER..... Caldwell 8" Maple S 36 W 14.5



" 8" J. Pine N 60 W 23.5

Seeley 30" W. Pine Stp N 72 E 25.8

AND

" 16" W. Pine Stp S 09 E 32.0

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during survey in this area. Found Schaaf pipe at corner as restored in 1934 survey. Used in all subsequent surveys. Both USBT stumps in place, poor condition.

SURVEYOR'S SEAL

SIGNED *Levitt Ostling* DATE 6-25-69  
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68