

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD


OSCODA COUNTY  
T 28 R 2 E

DESCRIPTION OF CORNER 1/4 CORNER COMMON TO SECTIONS 19-20

CORNER MONUMENT SET DEPT. MONUMENT

DATE MONUMENT PLACED AND WITNESSED 5-27-69

WITNESSES TO CORNER.....



7" R. Pine S 41 W 13.6

5" R. Pine N 38 W 41.9

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this area. Found 1½" pipe at corner as established in 1934 survey and used in other local surveys. Replaced with Department Monument.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE 6-25-69  
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68