

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD

OSCODA COUNTY


T 28 R 2 E

DESCRIPTION OF CORNER SEC. CORNER COMMON TO SECTIONS 19-20-29-30

CORNER MONUMENT SET DEPT. MONUMENT

DATE MONUMENT PLACED AND WITNESSED 5-27-69

WITNESSES TO CORNER.....



28" W. Pine N 70 E 71.9

7" R. Pine N 58 W 73.7

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this area. Originally restored by Seeley and accepted in subsequent surveys by Schaaf and Henning.

SURVEYOR'S SEAL

SIGNED *Keith Ostling* DATE 6-25-69
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68