

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


OSCODA COUNTY
T 28 R 2 E

DESCRIPTION OF CORNER 1/4 CORNER COMMON TO SECTIONS 32-33

CORNER MONUMENT SET DEPT. MONUMENT

DATE MONUMENT PLACED AND WITNESSED 5-27-69

WITNESSES TO CORNER..... 4" R. Pine S 72 W 1.25'



8" R. Pine N 33 E 20.9

12" R. Pine S 72 E 17.4

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this area. Found 1½" pipe at corner as restored by M. Schaaf from U.S.B.T. stumps which he identified in 1934. Replaced with Department monument.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Oetting* DATE 6-25-69
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68