

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD


OSCODA COUNTY  
T 28 R 2 E

DESCRIPTION OF CORNER SEC. CORNER COMMON TO SECTIONS 28-29-32-33

CORNER MONUMENT SET DEPT. MON.

DATE MONUMENT PLACED AND WITNESSED 5-26-69

WITNESSES TO CORNER..... 2" R. Pine S 04 E 65.6



4" J. Pine S 21 E 17.4

12" R. Pine Stp S 80 E 20.9

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this area. Found corner as restored in 1934 survey by Marcus Schaaf. Fits pattern of survey in this area better than Seeley's pipe, which was disregarded. No original evidence, although Schaaf had good corners South.

SURVEYOR'S SEAL

SIGNED *Conrad J. Ostling* DATE 6-25-69  
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68