

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


OSCODA COUNTY
T 28 R 2 E

DESCRIPTION OF CORNER 1/4 CORNER COMMON TO SECTIONS 28-29

CORNER MONUMENT SET DEPT. MONUMENT

DATE MONUMENT PLACED AND WITNESSED 6-2-69

WITNESSES TO CORNER..... 6" J. Pine S 35 W 33.3



4" R. Pine N 66 W 45.4

2" W. Pine S 18 W 36.6

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement during a survey in this area.
Schaaf pipe erroneously located and removed. No evidence.

SURVEYOR'S SEAL

SIGNED

Kenneth J. Deiling

DATE

6-25-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR #10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68