

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD


OSCODA COUNTY  
T 28 R 2 E

DESCRIPTION OF CORNER 1/4 CORNER COMMON TO SECTIONS 28-33

CORNER MONUMENT SET DEPT. MONUMENT

DATE MONUMENT PLACED AND WITNESSED 5-26-69

WITNESSES TO CORNER.....



13" Oak N 05 E 4.0  
5" R. Pine N 28 W 52.1

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement between section corners. Schaaf corner erroneous because of different section corners, and was removed. No original evidence.

SURVEYOR'S SEAL

SIGNED Keneth Ostling DATE 6-25-69  
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68