

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 corner common to Sections 22 - 27

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-23-69

WITNESSES TO CORNER.....



4" W. Pine N 79 W 12.5'

7" W. Pine South 22.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by proportionate measurement, midpoint on line between section corners. No U. S. evidence.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Levin A. Pelling
REGISTERED LAND SURVEYOR 10068

DATE

12-29-69

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68