

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E

DESCRIPTION OF CORNER 1/4 Corner common to Sections 22 - 23

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 12-23-69

WITNESSES TO CORNER..... 8" B. Cherry N 29 E 37.2'



36" W. Pine Stp N 50 W 14.8'

8" Tw W. Pine N 06 E 87.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by proportionate measurement, midpoint on line between sections corners, during a survey in this township. Nothing for U.S. evidence or a previous corner.

SURVEYOR'S SEAL

SIGNED *Levinth B. B. B.* DATE 12-29-69
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing