STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		OSCODA	COUNTY
		T <u>28 N</u>	R <u>2 E</u>
DESCRIPTION OF CORNER	1/4 corner common to Sect	ions 24 - 25	
CORNER MONUMENT	Set Dept. Monument		-
DATE MONUMENT PLACED AN	D WITNESSED 12-22-69		
WITNESSES TO CORNER	••		
N	7" Thornapple	S 66 E	63.8'
24	8" B. Cherry	N 38 E	76.6
	AND		
CIRCLE CORNER REGISTE	RED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set midpoint on line between section corners, during a survey in this township. Nothing else evailable. Corner falls about 56' North of trail road and 88' North of E-W fence.

SURVEYOR'S SEAL

STENED

DATI

2-29-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR #1006

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing