

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


OSCODA COUNTY
T 28 N R 2 E
T 28 N R 2 E

DESCRIPTION OF CORNER Section corner common to Sections 24-25-19-30

CORNER MONUMENT Left 1-1/2" pipe in concrete in place

DATE MONUMENT PLACED AND WITNESSED 12-23-69

WITNESSES TO CORNER.....



Cor Fence Post S 37 W 56.6'

Red top post West 32.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this township. Corner previously restored by Schaaf survey about 1935, and apparently found acceptable in subsequent surveys. Best available evidence. Falls about 26' North of center of road West, and 102' North of center of road East.

SURVEYOR'S SEAL

SIGNED *Levinth D. Oetting* DATE 12-29-69
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68