Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 28 N.R. 3 E

	_	Oscoda	COUNTY
DESCRIPTION OF CORNER _	Sec. corner common to Sections	s 31 & 32 on S. Bo	ındary
CORNER MONUMENT	Set Cons. Dept. Mon.		
DATE MONUMENT PLACED AND	D WITHESSED		
WITNESSES TO CORNER			
N	12" R. Pine	N 17 W	68.0'
31	8" R. Pine	N 85 E	20.71
CINCLE CORNER REGISTERED	AND		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by single proportionate measurement between corners one mile east and west. Unable to locate any conclusive evidence of a previous corner. USBTs all gone.

SURVEYOR'S SEAL

SIGNED LEWILLS SURVEYOR #10068

REGISTERED AND SURVEYOR #10068