MAR 1 9 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN OSCODA COUNTY FILED

	Filing Requir	ement of Act 74, Mich. P.A. 197	70 FILED
For corners in			14 NOV 96 1:51 P.M.
OSCODA (County)	Located In:	Carner Code ##	rings of Trafficette
₹Gaunty;	CLINTON TWP.		PATSY J. PETERS
1. Public Land Survey	T 28N P 3E	F-1	REGISTER OF DEEDS
	T R		
	τR		
	T R	A THE TANK THE TANK THE PERSON NAMED IN	•
2. Property Controlling	STR_ _A .	PHOVED	
in Section	S T R		Lihor 4 Page 128
3. Miscellaneous	s t r <u>Co</u> un	ly Remonumentation 1	Register of Deeds Stamp & File Number
Property in Sec.	S T RPe	er Review_Group_ L	
	Recorded Plat	C/4NOV96	
4. Lot No, I	Recorded Plat		- ABCDEEGHIJKLN
5. Private Claims			2 6 4 5 4 4 4 3 4 2 4 4
·			3
	•		4 7 4 9 4 10 11 12
PREDERICK J. KING	, in a field survey on June 28	. 19 96	5 1 1 1 1 1 1 1
do hereby certify that under re	quirements of P.A. 74, Michigan P.A	. of 1970, the corner points mentioned	6 18 17 16 15 14
		nd rules therefore as required in the ritment of the Interior, Bureau of Land	7
		er points mentioned in lines 3, 4 and 5	8 19 20 21 22 23 24
above were in conformance w	ith the rules of the Michigan Board	of Land Surveyors or by a Decree of a	
Court of Law; established, expressed below:	re-established, monumented, re-	monumented, recovered, found as	10 30 29 28 27 26 34
	anners all in the come town s	and range may be recorded	
on this certificate	corners, all in the same town a	ing range, may be recorded	12 31 32 33 34 35 36
On this certificate	:•	·	13
A. Description of original	monument and accessories ar	nd/or subsequent restoration:	
F-1 - NORTH 1/4 CORNER			
	nal Government Survey		·
in place f S 1/4 Sec Nov. 1972 - Act 74 by	for Randall's SE NBT & old f : 33 (29-3) - East 20.5' (Bk	nc line South - \$300E - 14.5° 1, Pg.55)	N track of E-W Rd., remains of Hemlock - 8" Maple - S60°E - 35.2' - 7" Maple c 4 (28-3) West - 20.5' Rec Bk 1, Pg 42
Cor F-13 (29-3)	. N. C	I DVD Mon - Bed 1 3 Pc. 763-76	4 - North -16.5' - DNR Post East-20.45'
560°E - 35	.1' - 5" Maple - \$30°E - 14	.5' - 8" Maple	F-13 (29-3) F-13 - Rec. L.4, Pg 350 - Same Witness
as Act 74	Rec. Bk 1, Pg. 55	e (Cap Gone) @ F-1 & Fnd DNR P	
Not Record	ied 20-45 *	East of F-1 @ F-13 (29-3)	@ F-13 & App. by Peer Review 5-13-94
Rec L. 12,	, Pg.87	Fnd Pipe (No Cap) 20.	53' W of f-13 @ F-1
B. Description of corn F-1 - NORTH 1/4 CORNER		thod applied in restoring or r	eestablishing corner:
North	Rec. Pipe (No Cap) - Placed - 16.5' (R&M) - DNR Post	i New Oscoda County Cap - (R) 5" Maple - NOW 15" Maple	in .
S30°E	- 14.5' (R) - 14.0' (M) - 20.5' \$ 20.45' (R) - 20	- (R) 8" Maple - NOW 18" Maple 0.53' (M) - Fnd Rec DNR Pipe &	e Cap @ F-13 (29-3)
C. th description of monum	ent for corner and accessories	established to perpetuate locating	faithful establishment of the position of the position of the corner:
F-1 - NORTH 1/4 CORNER			OF MICL
North - 16.8' -	da Co. Cap on existing Pipe - DNR - Red Top Post	found (Bk I, Pg. 55)	TE OF MICHIGAN
	- Fnd Tag #13410 - E side 12	2" Maple 💮 🏄 🏄	FREDERICK * * *
	- Fnd Tag # 25852 - SE side		J. KING TE
	- Fnd Tag #25852 - NE side	18" Maple	SURVEYOR POR
	- Set S&T NE side 15" Maple		No. / w B
EAST - 20.53' -	Rec DNR Pipe & Cap at Cor	L-19 (C249) T	25852

Surveyor's Michigan License No. 25852

Date <u>October 26. 1996</u>

OFESSION

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983