

Liber 4 Pg 114

MAR 1 9 1997

Fo		ng Requireme	ent of Act 74, Mich. P. Corner Code #	<del>-</del>	STATE OF MICH OSCODA COUN FILED		
1.	Public Land Survey	inton Twp.  V R 4E  R  R	<u>C-1</u>	1	.7 SEP 96 9:4 PATSY J. PE REGISTER OF	TERS	
3,	Property Controlling S T	_ R _ R _ R		Register of D	PAGE 5/15 eeds Stamp &	)C File Number	
4.	Lot No, Recorded Plat	<del></del>		A B			14
5.	Private Claims	<del></del>					٦
do l in li mai Mai	Larry G. Beauregard , in a field survey on nereby certify that under requirements of P.A. 74, nes 1 and 2 above were in conformance with regular of survey instructions of the United States and the court of Law and the c	Michigan P.A. of ulations and rules to ites. Department or that the corner	therefore as required in the coordinate of the Interior, Bureau of points mentioned in lines 3.	current 7 4 and 8 19	-17 - 1620 - 21 -	-101112- -151413- -232324	
5 al	pove were in conformance with the rules of the ree of a Court of Law; established, re-establishe	Michigan Board	of Professional Surveyors of	orbya 9			_
as e	xpressed below:	ia, monumentea, i	e-monumented, recovered,	10 10 10 10 10 10 10 10 10 10 10 10 10 1	29 28	-272625-	_
NO	TE: Not more than 4 corners, all in the sam on this certificate.	e town and rang	ge, may be recorded	11 12 31 13	32-33	34 35 36	-
A.	Description of original monument and acc C - 1 Corner common to Section 5 an	cessories and/o d 6.	r subsequent restoratio	n:		,	_
	No bearing trees Convt.  1913 C.O. Seeley Oscoda Co. surveyor set subdivision post 34 links W. of std. cor. Sec. 31-32 T29N. R4E: No wit's mkd  1981 Norman C. Caldwell P.S. # 12018 set Oscoda Co. Std. Corner ( 3" brass cap on 1" x 3' pipe ) 22.44' West of  Std. corner common to Section 31 and 32 T29N, R4E, Survey recorded L. 3, P. 296 & 297 Oscoda Co. Records.  LCRC recorded L. 1, P. 255. Corner References: ( S 45°W 1.0' DNR post.) (East 22.44' Sec. cor. 31-32, T29N, R4E.  No other suitable references available.						
В.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:						
	Found Oscoda County std. corner set by Caldwell in good condition with DNR post & location marked along side.						
	This corner is 22.44' feet West of std. corner for Section 31 - 32, T 29N. R 4E.						
		AP	PROVED	11.6	LARRY      BEAURE	GARD *	-
		County Peer	Remonumentation Review Group	SEP 1 56	SURVE NO. 1865	W	
C.	Description of monument for corner and Corner common to Section 5 & 6 Oscoda Co. std corner, 3" brass cap position of the corner. Approved by	on 1" x 3' pir	e. Accepted as a care				
	East 22.44' Concrete Monument Sec. N 42° E 97.93' 4" Maple S 35° E 70.35' 14" Poplar N 80° E 14.63' 14" Poplar S 20° E 45.84' 6" Poplar	cor. 31-32, 7	29N, R 4E				
	Placed 60d penny spike and P.S. tag	#18654 (typ)					
Sig	ned by Jany Bea	ungand	, Date _	9-4-19	96		
Sur	veyor's Michigan License No1865	4 0		PPROVED BY MICHIGAN STATE BO		SURVEYORS, JAN. 28, 1971	-
						REVISEO MAY 14, 1975 REVISED JAN., 1983	