MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T.29. NR.1.Y...

				COUNTY
DESCRIPTION	OF	CORNER	Section Corner common to Sections	15,16,21,22
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4"_Bress of	tap
WIT TNESSES	то	CORNER	10" J. Pine - S 2 F + 20 Links	
			_ 10* J. Pine = N 87 W60 Links _	
			,	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Corner had been previously located and perpetuated, by G. F. DelaMater, Registered Land Surveyor, of Gaylord. Remains of one original B.T. still in place, badly burned.

Corner was placed and witnessed August 21, 1952.

SURVEYORS SEAL

SIGNED Jean C. Jefnalu DATE 2/20/53 _