

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 29 N.R. 1 W


Otsego COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 29-30

CORNER MONUMENT Set Cons. Dept. Mon.

DATE MONUMENT PLACED AND WITNESSED 4/12/68

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

10" J. Pine S 33 E 7.2

10" B. Oak S 60 W 22.0

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored according to record of 1926 survey by E. S. Houghton, who located this corner at old fence corner. Recovered corner fence post which checks measurement from Section corner south. Nothing left for U.S.B.T.s.

SURVEYOR'S SEAL

SIGNED

Kenneth B. Kelly
REGISTERED LAND SURVEYOR #10068

DATE

4/22/68