CONS. 4047

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

\_ \_\_\_\_\_\_

LAND CORNER RECORD

T 29 NR 2 W ---

		OtBego	COUNTY
DESCRIPTION OF CORNER	Section corner com	môn to Sections	2-3-34-35
DESCRIPTION OF CORNER	MONUMENT 1" pipe	Mitu Ha prass c	ap
WITNESSES TO CORNER .		884E 62	½_Links
	5" Maple -	816W - 15	Links
	• 30" W. Pine stump	East 91	_ 19nks
	• G.F.DeLaMater wit	ness 1937	
	•		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was previously restored from the government BTs by G. F. DeLaMater, Otsego County Surveyor, in 1937. Corner was remonumented and witnessed by Forestry Division Land Surveyor for easier identification of state land boundaries and to perpetuate a government corner.

Corner was placed and witnessed April 27, 1959.

SURVEYORS SEAL

SIGNED KESISTERED LAND SURVEYOR DATE 4/28/59