## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_29\_ NR\_2 W\_\_\_

		Otsego		COUNTY
DESCRIPTION OF COR	NER Section co	rner common t	o Secti	on <b>s</b> 16-17-20-21
DESCRIPTION OF CORN	IER MONUMENT	I" pipe with	ha pras	e_cap
WITNESSES TO CORNI	ER	. <b>.</b>		
	9" Cedar	- S14E	<b>-</b>	69 links
·	20# W. Pine	West	<u>-</u>	42 <del>1</del> links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was monumented and rewitnessed by Forestry Division Land Surveyor to perpetuate a known corner and identify state land boundaries. Found a 2" par at corner with NBTs NW and SW. Unable to identify government BTs.

Corner was placed and witnessed May 8, 1959.

SURVEYORS SEAL

SIGNED REGISTERED LAND SURVEYOR DATE 5/11/59