

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 28. NR. 3. W.  
T. 29. NR. 3. W.

Osage COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 4, 5, 32, 33

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER 6" S. Maple - S 48 N - 67 Links

24" W. Pine Stub - N 51 E - 89 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while working in this area. Found remains of original stake. Unknown Surveyor had previously re-witnessed corner, but had left no corner marker.

Corner was placed and witnessed December 7, 1951.

SURVEYORS SEAL

SIGNED *John C. [Signature]* DATE 1/15/52  
REGISTERED LAND SURVEYOR