MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T__28 NR__4_W-T 29 NR 4 W

			CtaegeCOUNTY
DESCRIPTION	OF	CORNER	_Section Corner common to Sections 5,6,31,32
DESCRIPTION	OF	CORNER	MONUMENT_Im_Pipe_with_Aw Bress cop
WITTNESSES	то	CORNER	_ 7%_ Ceder - 8-59 W 51 Links
			10" Balsan - 8 7 E - 24 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey cree, while working in this area. Corner had been previously located by unknown Surveyor. Two original B.T.'s in place, in poor condition.

Corner was placed and witnessed December 4, 1951.

SURVEYOR'S SEAL

SIGNED SIGNED DATE 1/15/52 _