

MAR 17 2000

OTSEGO COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Also Act 345, PA 1990

OTSEGO COUNTY RECEIVED FOR PECCEN

For corners in

4. Lot No.

Otsego	Located in:	Corner Code #		
(County)	Chester Township			
1. Public Land Survey	T <u>30N</u> R <u>2W</u> T R T R	A-6		
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R			

Recorded Plat

80:01 MA 01 HAL 00

CLERK / REGISTER OF DEEDS

Register of Deeds Stamp & File Number

ō.	Private	Claims		 	 	

James L. Schwandt , in a field survey on <u>Jan. 19</u>, 19<u>99</u>, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 5 7 8
- A. Description of original monument and accessories and/or subsequent restoration:
- G.L.O. Harvey Mellen, 1856 Set Post 8" Beech N36°W, 15 links (9.90') 6" Beech \$49°W, 26 links (17.16')
- County Survey Record, 4-190 John Fisher, 1902 18" Hemlock, N62°E, 40 links (26.40') 24" Sugar, N88°W, 29 links (19.14')
- County Survey Records (2-56) David Hoffman, 1905 18" Hemlock, N62°E, 40 links (26.40') 24" Sugar, N88°W, 29 links (19.14')
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 2" Iron pipe PP, N37°E, 61.67' Fence post, S35°E, 41.58' Fence post, N87°E, 27.10'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set OCM over 2" iron pipe and is accepted as the best available evidence of the position of the original corner. PP, N37°E, 61.67'

Fe Po, S35°E, 41.58' Fe Po, N87°E, 27.10'

North gate post, N47°W, 69.25'

Date 12-28-99

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197

OTSEGO COUNTY REMONUMENTATION

REVISED MAY 14,197 REVISED JAN., 198 REVISED OCT., 199

Approved by the County Survey Peer Group, pursuant to Act 345, PA 1990.

