MAY 2 8 1997

OTSEGO COUNTY REMONUMENTATION

COMMISSIUM

LAND CORNER RECORDATION CERTIFICATE

| · · · · · · · · · · · · · · · · · · · | • | uirement of Act 74, Wilch. | | | | |
|---|---|---|-------------------|-----------------|---------------------------|--------|
| For corners in | A | ALSO ACT 345, PA | 1990 | | O COUNTY | |
| Otsego | Located in: | Corner Code # | | | HIGAN FOR RECC | ORD |
| (County) | Bagley Townsh | ırb | | | | |
| 1. Public Land Survey | T30NR3W T R | B-5 | | | 0 PM 2: 1 | 15 |
| 2 Danuarda Cantra Nina | T Resolution Resolution | | | CLERK / REG | N M. PRATT ISTER OF DE | EEDS |
| Property Controlling in Section Miscellaneous | S T R | | | | | |
| Property in Sec. | S T R | | Regis | ter of Deeds Si | tamp & File I | Number |
| | rded Plat | | A B 6 2 6 6 | C D E F G | H I J | K L : |
| under requirements of P.A. 74, above were in conformance wit | , Michigan P.A. of 1970, the cor th regulations and rules therefor | . 17 19 96 do hereby centif mer points mentioned in lines 1 a e as required in the current mand | and 2 ual of 5 | 89 | 1011_ | 12 |
| survey instructions of the United decree of a Court of Law and / conformance with the rules of th | ere in | 17 16 | 15 14 | 13 | | |
| established, re-established, mon | iumented, re-monumented, recov | ered, found as expressed below: | B — 19— 9 — — | 20—21 | 2223 | 24- |
| | | | 10—30— | 29 28 | 27 26 | 25 |
| | | | 11 | 32 33 | 3435 | 36- |
| A. Description of original mo | onument and accessories and | d/or subsequent restoration: | 13 | <u> </u> | | 1 1 |

B-5 T30N-R3W GLO (1-380) Addison Brewer, 1856 Set Post Sugar 18" N72°E, 21 Links (13.86') Sugar 16" S48°W, 34 Links (22.44')

Gerald McKelvey, 1974

LCRC (1-369)

Fnd 3/4" Pipe at Approx Govt Distance & Line Tag in 3" Pine N45°E, 40.66'

Tag in 36" Elm South, 47.38'

Tag in SW Side 4" Pine S30°E, 36.01'

RS (507-307) C.I. Robinson, 1976

Fnd 3/4" Pine & all Gerald McKelvey Wits Set O.C.M.

Unrecorded Survey C.J. Robinson, 1985 Fnd Pieces of O.C.M. Reset O.C.M. from 1/2" Rod & Elm References 8" Pine S50°E, 36.03' 36" Elm S05°E, 47.78' 7" J. Pine N30°E, 46.78'

B. Description of corner evidence found and/or method applied in restoring or reastablishing corner:

No Evidence of O.C.M. (Road was Recently Resurfaced); Found Indication of East Side of 36" Elm; No Other Witnesses were Found Using Coordinates Supplied by C.I. Robsinson for A-5, B-5 & C-5, a Traverse was Run Between A-5 & C-5 to Place Corner @ B-5

C. Description of monument for comer and accessories established to perpetuate locating the position of the corner:

Set O.C.M. @ computed position, and is accepted as a careful and faithful reestablishment of the position of the original corner.

Centerline of Millbocker Road, South, 12' Set Spk in 36° Elm South, 49.90' Set Spk in 12" R. Pine S33°W, 54.05' Set Spk in 7" J. Pine N50°E, 55.18' Fnd Nail in 10" J. Pine N35°E, 44.75' Set Spk in 8" J. Pine N25°W, 60.65'



OTSEGO COUNTY REMONUMENTATION

Approved by the County Survey Peer Group, pursuant to Act 345, PA 1990. DEC 20,1996 Date Chairman

| Date | 17-20-96 |
|------|----------|
| Date | 70.00 /0 |

| Signed by | James | Aldu. | ravdt |
|------------|------------|------------|-------|
| Surveyor's | lichigan L | icense No. | 2 |

26466