## LAND CORNER RECORDATION CERTIFICATE

|  |  | LAND CORNER Filing Requirem   | ent of Act 74, Micl   | 1. P.A. 1970   | OTSEGO CO   | QUNTY  |  |
|--|--|---|---|--|---|--|--|
| For corners in   |  |   |   |  | RECEIVED FOR  | a <b>n</b><br>Lagoran  |  |
| Otsego<br>(County)   | Located In:  | Corner 6  | Code #  |  | 95 DEC 27 A   | 1 9: 39  |  |
| 1. Public Land So  | urvey T;<br>T;<br>T;<br>T;   | ON R 3W<br>R R<br>R   | E-6   |  | CLERK/REGISTER  | RATT<br>OF DEEDS   |  |
| Property Cont<br>in Section     Miscellaneous<br>Property in Section   | s !<br>s Ţ   | R<br>R<br>R   |   |  | Register of Deeds Sta   | mp & File Number   |  |
| 5. Private Claims  I, James L. Schw requirements of P.A conformance with A   | andt , in a field standard and tunes of the Interior, Bureau its mentioned in lines 3, 4 an interior and tunes and t | invey on October 13<br>the corner points menti<br>as required in the current<br>of Land Management or | , 19 95 do hereby sta<br>oned in lines 1 and 2 a<br>t manual of survey instru<br>by a decree of a Court o | te that under<br>bove were in<br>actions of the<br>f Law and /or<br>the Michigan | A B C D E F G  2 6 5 4 3  4 7 8 9 9 5 6 18 17 16 7  | H I J K L M  |  |
| that the corner point<br>Board of Land Sur<br>recovered, found as  | vevors or by a Decree of   | a Court of Law; establi   | shed, re-established, r   | nonumented,  | 9 20 21   | _222324  |  |
| on this c  | ertificate.  |   |   |  | 10 - 30 - 29 - 26<br>11 - 12 - 31 32 33 13  |  |  |
| A Description o  | of original monument and   | accessories and/or su   | ibsequent restoration   | r:   |   |  |  |
| E-6<br>G.L.O. Ad<br>Set Post<br>14" Beech  | 1300-1300<br>Idison Brewer, 1856<br>n East 39 links (25.74')   | John M. Sanborn, 18<br>14″ Beech East 40 li<br>15″ Sugar S54°W 49                                     | 384<br>nks (26.401)   | G.F. Del<br>6" Suga  | lamater, 1923<br>r S64°E 37 links (24.42')<br>ct S74°E 50 links (33.00')<br>r N69°E 55½ links (35.63')  |  |  |
| 15" Sugar S54°W 49 links (32.34')  Poter E. Chenard #14200  November 12, 1976  Fd. W" iron in centerline  Conc. Mon. S81°E 40.54'  Notch R.R. sign N18°W 100.29'  Gas line marker S65°E 43.29' |  | Add witness   | James L. Schwandt #26466, 1977<br>Add witness<br>R.R. Rall S15°E 93.44′                                   |  | Carl I. Robinson #16390 July 1, 1992 Set 20d Spk. & nut in timber grade crossing on pavement centerline 10' of south rall Gas line marker S65°E 43.49' L. Pole S11°E 82.56'; P.P. N86°W 130.47' Notch in R.R. sign post N18°W 100.29' |  |  |
| B. Description   | of corner evidence found   | and/or method applie  | ed in restoring or rees   |  |   |  |  |
| E-6  | Fd. Hole in Timber at le<br>ir. P.E.C. can not be ve   | ecation wit by C.I.R. it  | 1992. Location can  | be traced back   | to P.E.C. 1/2" lr. Fd. In   | 1976. Origin of  |  |
|  | Fd. Notch in R.R. sign<br>Fd. Gas line marker S6<br>Fd. R.R. Rail S15°E 93.  | post N18°₩100.29′<br>5°E 43.49′   |   |  |   |  |  |
|  |  |   |   |  |   |  |  |
| C. Description   | of monument for corner a   |   |   | -A-W   |   |  |  |
| E-6  | Set 60-d. Spike in R.R. Timber  Fd. Notch in R.R. sign post N18°M 100.29'  Fd. Gas line marker S85°E 43.49'  Fd. R.R. Rail S15°E 93.44'  Set Tag in P.P. S11°E 82.00'  And is accepted as a careful and faithful reestablishmen  |   |   | up, pursuant 1<br>15,1135 C<br>Date  | County Survey Peer o Act 345, PA 1990. Chairman   | THE OF MICHIGAN  |  |
|  | And is accepted as a c   | areful and faithful ree   | stablishment of the p   | osison of the C  | *   | SCHWANDT<br>PROFESSIONAL   |  |
| Signed by  | mes of Survey  | udt_  |   | Date 12-2  | 71-95   | No.<br>28466   |  |
| Surveyor's Mic   | higan License No.  | 26465   |   |  |   | Annual Contract of the Contrac |  |
| V  |  |   | FORM A  | PROVED BY MICHI  | GAN STATE BOARD OF PROFESS  | ONAL SURVEYORS, JAN. 28, 19,   |  |