LAND CORNER RECORDATION CERTIFICATE

				DATION CERTIFIC ct 74, Mich. P.A. 1		ots	EGO COUNT	ΤΥ.
For corners in		g , 10	quiiomont or 7 t		0.0	RECEIV	fichigan En for de	CORD
Otsego (County)	Located In	:	Corner Code #			95 DEC	27 AM 9	: 40
1. Public Land Surve	ey T T T	30N R3W RR	I-8	 		CLERK/R	E GISTER OF	T DEEDS
Property Controlli in Section Miscellaneous Property in Sec.	T R							Number
4. Lot No,	Recorded Plat				A B C	: D E F	GHIJ	тк ем
5. Private Claims					2 6	5 4-]	
					3			
I, James L. Schwandt requirements of P.A. 74,	in a field su Michigan P.A. of 1970,	rvey on Octob the corner point	er 11, 19 <u>95</u> do s mentioned in lines	hereby state that under 1 and 2 above were in	4 - 7 -	- ė b 	<u> </u>	11'2
conformance with regulation United States Department					5 18	_1716_	15-1-1	413
that the corner points me Board of Land Surveyors					7		1-1-1	
recovered, found as expre-	ssed below:				8 -19	2021- 	22-4-2	3
NOTE: Not more than on this certifica	ime town and i	range, may be reco	erded	9 1030	2928-	2721	5—25—	
	••••				11			
					12 31	3'23'3_	34-35	36-
A Description of origin		ccessories and	Vor subsequent re	storation:	131			
G.L.O. Addison Brewer, 1856 Old Post 10″ Hemlock N30°E 17 (11,72′) 8″ Beech N87°W 34 (22.44′)		John I. Nelson #21273 - April 2, 1976 Fd. "T" iron w/metal RLS cap by Delamater. Corner falls on N-S fence w/no E-W occupation and is 17'East of centerline of Krys Road 24' gravel. Corner agrees w/G.L.O. distance on East section line. (1) Set nail w/RLS Tag South side 3" Red Pine						
Carl I. Robinson October 19, 1985 Set O.C.M.		AZ. 95° 56.88 (2) Set nail v	g W/RLS Tag SE side W/RLS Tag NE side	e 6" Red pine AZ. 222 e 6" Red Pine AZ. 300	° 59.94′ ° 43.31			
B. Description of corn	er evidence found an	d/or method a	pplięd in restoring	or reestablishing con	ner:			
I-8 Fd. Broken O.C.M. set by C.I.R.in Mon. Box in 1985 at witnessed location. Mon. Box set by Do Fd. A Delamater capped T-Ir. In 1976. Delamater notes not Fd. No direct tie to G.L.O.						n Sagasser, I	S OCRC. J.I	.N.
Fd. B Fd. B	Iz & Tag 8" R. Pine I Iz & Tag 8" R. Pine S	160°W 43.33° 542°W 60,00°						
			•					
C. Description of monu	ment for corner and	accessories es	stablished to perpe	stuate locating the pos	sition of the c	orner:		
	roken O.C.M. in Mon.		is.					
Fd. Bi Set Bl:	lz & Tag 8" R. Pine N iz & Tag 8" R. Pine S z & Tag 6" R. Pine S z & Tag 10" R. Pine S	42°W 60.00′ 39°W 38.43′	į			فد	OF Mo	
And is	accepted as a carefu	ıl and faithful :		the position of the o		13	JAMES L.	IIC.
				the County Survey ant to Act 345, PA		1-1	SCHWAND	
Signed by	est Schwa	udt	<u> でた - ルミルン</u> Date		<u></u>	CENS	BURVEYOR No. 26488	10
James . So Surveyor's Michigan Lice	chwandt, PS ense No.	26466		_			OFESSIONA	SIL
V							- 3310	