MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 30 NR 4 J

	OtsegoC	TAUC
DESCRIPTION OF COR	RNER 1/4 corner at center of Section 14	
DESCRIPTION OF CORE	NER MONUMENT tupe with 4" brass cap	
WITNESSES TO CORN	IER	
	BT 6" Ironwood - SSSW - 33 links	
	BT 36" W. Pine stub - N13W - 130 lin	ķs

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew while making a survey of Section 14. Set corner at intersection of true 1/4 lines. This point appears to be about three links NE of a possible location of the center as established by Sanborn in 1883. A large Hemlock, standing but nearly dead, in place for Sanborn's SE witness—but could find no evidence of a post. After consideration, it was concluded that our resurvey more accurately designates the proper location for the center post, since no other monumentation prevailed.

Corner was placed and witnessed 10/9/59.

SURVEYOR'S SEAL

SIGNED LEMES DATE 10/15/59_
REGISTERED LAND SURVEYOR