

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 30. NR. 4 W. . . .

Otsego

COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 13 and 14 . . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . .

WITNESSES TO CORNER . . .

36" W. Pine stump - S41E - 43 1/2 links

Both G.F. DeLaMater NBTs in place

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner was found by Forestry Division survey crew while making a survey of Section 14. Found a 1/2" iron bar at corner, previously established by G.F. DeLaMater in 1934. This point apparently is intended to perpetuate the corner as identified and restored by Sanborn in 1883. Sanborn's 40" W. Pine remains in place NW, but government BTs gone. Corner conforms to pattern of previous subdivision.

Corner was placed and witnessed 10/9/59.

SURVEYORS SEAL

SIGNED

*Kenneth J. Ostler*  
REGISTERED LAND SURVEYOR

DATE 10/15/59