Comer Code ##

	Filing Requ	uirement of Act 74, Mich.	P.A. 1970
For corners in	AL	SO Act 345, PA 1990	
OTSEGO	l costed in:	Comer Code ++	

OTSEGO COUNTY MICHIGAN RECEIVED FOR RECORD

94 DEC 14 PH 4: 00

EVELYN M. PRATT CLERK / REGISTER OF DEEDS


T 30 N R 4 W 8-3 1. Public Land Survey T _____ R ___ R _ R Τ. Τ. _ R _ 2. Property Controlling Τ_ _R. in Section S s _ TR _ 3. Miscellaneous s Property in Sec.

Located In:

Register of Deeds Stamp & File Number

4. Lot No. _ , Recorded Plat 5. Private Claims

_ , 19 _94 Carl I. Robinson October 11. . . in a field survey on . do hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, lound as expressed below:



NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - GLO 1/508: A.P. Brewer, 1856: Post- Elm 36 N 65°E 9 lks (5.9'), Elm 16 S 55°W 7 lks (4.6').
 - CSR 1/50: A.W. Bates, 1890: Found Gov't B & P-Sugar 24 S 111 °E 67 lks (44.2'), Sugar 12 N 3°E 911 lks (60.4').
 - CSR 2/184: Hoffman ?, 1919: Plow Point in corner, found Bates stump NE & root cores to SE-Sugar 12 N 4°W 1.36% ch (90.1') "nothing else to be had".
 - LCR 2/222; C.I. Robinson, 1980: found Plow Point 12" below asphalt & 20" Sugar Maple stump N 4°W 89.2'-set Otsego County Monument, spk P.Pole South 33.72', spk 12" Maple N 50°W 50.39', spk 4" Cherry North 53.66', spk 10" Tw. Maple N 40°E 51.69'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Otsego County Monument 1" below pavement surface (adjusted with riser) and P.Pole, Maple & Tw.Maple references. Also fits G.F. DeLamater distance to east (C-3).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


Otsego County Monument in road centerline flush with pavement surface is accepted as a careful and faithful perpetuation of the position of the original corner.

CARL 1. ROBINSON

ROFESSION BURVEYOR

16390

spk 14" & 20" Tw. Maple N 40°E 51.46', spk P.Pole South 33.68', spk 20" Maple N 50°W 50.32', spk 18" Maple N 18°W 68.08'. NE OF MICHIG



ESSIONA Carl I. Robinson, PE & Surveyor's Michigan License No. 16390

November 25, 1994