APR 2 5 1995

## COMMISSION

## OTSEGO COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

TOT COITICIS III		ALSO ACT 242, TA 1220		
_	OTSEGO (County)	Located In:	Corner Code ##	OTSEGO COUNTY MICHIGAN
1.	Public Land Survey	T_30 N R 4 W_	D <b>-</b> 5	RECEIVED FOR RECORD
	·	.T R		94 DEC 14 PM 4: 01
		T R		S JANYIG M PRATT
2.	Property Controlling	S T R	2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -	EVELYWM. PRATT CLERK / REGISTER OF DEEDS
	in Section	S		
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number

Property in Sec. S \_\_\_\_ R \_ 4. Lot No. \_\_\_ , Recorded Plat . 5. Private Claims \_ Carl I. Robinson current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: GLO 1/506: A.P. Brewer, 1856: Post-Sugar 9, N 91°E 13 lks (8.6'), Elm 8 S 61°W 32 lks (21.1'). LCR 2/125: G.R. McKelvey, 1978: GLO corner & references not found, set Otsego County Monument at MPOL S. Sec. linespk 8" Maple N 72°W 19.33', spk 8" Maple N 53°E 6.57', spk Quad. 10" Oak clump S 28°W 12.40', spk 10" Maple S 44°E 38.64'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Otsego County Monument 2'± South of fence to east & west & all McKelvey's 1978 witnesses. Found old tree mound N  $9\frac{1}{2}$ °E  $9'\pm$  which could be GLO Sugar reference.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Otsego County Monument 2'± south of fence to east & west is accepted as a careful and faithful reestablishment of the position of the original corner.

spk 8" Maple N 53°E 6.57', spk 12" Maple S 44°E 38.64', spk 10"-15" Quad Basswood S 28°W 12.34',

PLE OF MICHICAL ROBINSON ROFESSIONAL SURVEYOR 16390

## OTSEGO COUNTY REMONUMENTATION

Approved by the County Survey Peer Group, pursuant to Act 345, PA 1990. 194 Date V. Chairman

OFESSION P December 13, 1994

I. Robinsor Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983