MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_31 NR_1 N. T 32 N R 2 W

			QtgegoCOUNTY
DESCRIPTION	OF	CORNER	1/A Corner between Sections 7 & 12
DESCRIPTION	OF	CORNER	MONUMENT1"_Pipe_with_4" Brass_cap
WIT TNESSES	то	CORNER	8" Ceder - N 78 E - 59 Links
			_ 18" Red_Pine_Stub = N 55.W9-Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner had been previously located and perpetuated by Marous Schaaf, Registered Land Surveyor. One original B.1. in place, in good condition.

Corner was placed and witnessed July 11, 1951.

SURVEYOR'S SEAL

SIGNED Seem C. Such mater DATE 1/15/52