MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T__ 11 NR_ 1. # ..

			Otage COUNTY
DESCRIPTION	OF	CORNER	_ Section Corner.common_te_Sections_14,15,22,23
DESCRIPTION	OF	CORNER	MONUMENT_1 Pipe with 4 Bress cap
WITTNESSES	то	CORNER	_6"_\$press8_6_K = 128_Links
			_8" Relsen - N. 67 F - 21 Links
			_6"_Balsen - & 81 E - 46 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner had been previously located and perpetuated by Marcus Schaaf, Registered Land Surveyor, from original B.T.&s. One original B.T. still in placed in good condition.

Corner was placed and witnessed April 17, 1951.

SURVEYOR'S SEAL

SIGNED Sear C. Set mater DATE 1/15/52